


Marathwada Plumbing & Thermal Scanning Services

Thermal Scanning Report



Inspection prepared for: Customer

Date of Inspection: 31 May 2026 | Time: 12:30 PM

Inspector: Haidar Munjewar


Service Location: Pune & PCMC

Living Room


Observation: Moisture patterns noted on the ceiling.




Live moisture on ceiling



Live moisture on ceiling



Thermal image of live moisture on ceiling




Thermal image of live moisture on ceiling

Kitchen

Observation: Water dripping noted on the ceiling.



Water dripping from ceiling




Thermal image of water dripping from ceiling

Children's Bedroom

Observation: Water dripping and moisture damage noted on the ceiling.



Water dripping from ceiling



Thermal image of water dripping from ceiling




Thermal image of water dripping from ceiling

Common Bathroom


Observation: Leakage signs noted around a plumbing line.



Leakage from pipe line



Water oozing out from duct wall



Thermal image of water leakage from pipe line